



Worldwide repairs carried out with PolymerMetal®

REP-# 035



The upper part of an impeller of a pump for filling up the ready cement in sacks was exposed to very strong wear and tear. In the meantime it was tried to restore by build-up welding. The final repair has been carried out with Ceramium and Hardener CE.

MultiMetall
the MetalExistenceCompany®