




Worldwide repairs carried out with PolymerMetal®

REP-# 042



The surface of a transformer between copper plates and fibreglass coating showed several oil leakages. The repair has been affected using the direct-MM-bonding method with MM-metal oL-steelceramic combined with Hardener red and Hardener yellow afterwards.

MultiMetal
the MetalExistenceCompany®