

REP-#154



Oil exuded through micro cracks caused by vibration in a defective welded seam. The leak of oil has amplified after unsuccessful attempt to execute repair by usual welding. Then it was decided to carry out a repair by using the "direct-MM-bonding"- technology with the help of MM-metal oL-steelceramic and hardener red followed by a second layer of MM-metal oL-steelceramic with hardener yellow.

MultiMetal
the MetalExistenceCompany®