



Worldwide repairs carried out with PolymerMetal®

REP-#156



The welding at 19 places of transformers had micro cracks and blowholes, where oil exuded. First the paint has been removed with an electro drill equipped with an abrasive tool and the metal has been cleaned at the defective areas. Then MM-metal oL-steelceramic with Hardener red and afterwards Hardener yellow was applied. After checking the tightness of the repaired areas the corresponding areas have been painted over again.

MultiMetal
the MetalExistenceCompany®