



Worldwide repairs carried out with PolymerMetall®

REP-# 170



The pump capacity of a diesel pump decreased due to a leakage. There was a small leak probably resulting from an untight soldered seam or a crack in the copper pipe at a difficult accessible repair place at a measuring plug. A soldering/welding linked the measuring steel plug (diameter approx. 25 mm) with a 3/4-inch copper pipe. By using MM-metal SS-steelceramic and Hardener yellow the damage was repaired and later the customer (a water treatment company) put the pump into operation again with the usual working pressure of 16 bar.

MultiMetall
the MetalExistenceCompany®