



Worldwide repairs carried out with PolymerMetal®

REP-# 027



Repair of two tail bearings of a propeller shaft by using MM-metal SS-steelceramic, Hardener yellow and Hardener green. A ring with exact interior diameter has been bolted to both sides of the bearing. This ring has been centralized to the ideal shaft axis. Then MM-metal SS-steelceramic has been applied and been stretched parallel to the axis.

MultiMetall
the MetalExistenceCompany®