



Worldwide repairs carried out with PolymerMetal[®]

REP-#145



A reeling machine was worn out due to abrasion. After roughening the surface to be treated, it was coated with the PolymerMetal MM-metal SS-steel and therefore put into working order again.

MultiMetal
the MetalExistenceCompany[®]