






Worldwide repairs carried out with PolymerMetal®

REP-# 036



The contact surfaces of a supercharger have been rebuilt with MM-metal SS-steelceramic and Hardener yellow.

MultiMetal
the MetalExistenceCompany®