



Worldwide repairs carried out with PolymerMetal[®]

REP-# 010



Sealing of cracked leaky welding seams at crankcase of a ship diesel with MM-metal SS-steelceramic and Hardener yellow.

MultiMetall
the MetalExistenceCompany[®]