



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 071**



Repair of the bottom part of a coal mill. The repair has been carried out both with Ceramium pasty and Ceramium liquid.

**MultiMetall**  
the MetalExistenceCompany®