



Worldwide repairs carried out with PolymerMetal®

REP-# 074



Repair of an oil / gas tank under arctic temperature. The repair was carried out with MM-metal UW and Hardener UW3 in Russia.

**MultiMetal**  
the MetalExistenceCompany®