



Worldwide repairs carried out with PolymerMetal®

REP-# 088



A machine casing was repaired by using MM-metal oL-steelceramic and Hardener red and afterwards Hardener yellow. The application has been done using the direct-MM-bonding technology.

MultiMetal
the MetalExistenceCompany®