



*Worldwide repairs carried out with PolymerMetal®*

**REP-# 105**



Coating of a turbine impeller due to cavitation damages. Here the materials Ceramium and Hardener CE were used.

**MultiMetall**  
the MetalExistenceCompany®