



Worldwide repairs carried out with PolymerMetal[®]

REP-#143



Several valves of a line system on an oil platform were damaged. The problem was abrasion caused by the transportation of sand and sea water. The damages were repaired with the help of Ceramium, pasty.

MultiMetall
the MetalExistenceCompany[®]

MultiMetall • P.O. Box 12 02 64 • 41720 Viersen • Germany
Tel: +49 (0) 21 62-97 00 9-0 • Fax: +49 (0) 21 62-97 00 9-11
Email: info@polymermetal.com • Web: www.polymermetal.com