



Worldwide repairs carried out with PolymerMetal®

REP-#149



Due to abrasion a worn out metal ring of a dredging pump had to be replaced. With the help of MM-metal SS-steel the new metal ring was fixed. PolymerMetals present a high shearing strength; MM-metal SS-steel offers a value 30 MPa.

MultiMetal
the MetalExistenceCompany®