



## Worldwide repairs carried out with PolymerMetall®

## **REP-#164**





In a refinery located in the north of Germany (capacity ~ 4.500.000 tons crude oil per year) a spindle oil cooler respectively a pipe bundle was coated at the areas marked red. The facility with the concerned assembly is used for the crude oil distillation for the production of benzine and kerosene. Products like VP 10-017 and further polymer materials manufactured by MultiMetall are applied for more than 25 years in the refinery sector of the respective affiliated group Texaco/Shell. To this repair there is available a scale-up of the drawing upon request.

## MultiMetall the MetalExistenceCompany®